

NTMP Data Summary Sheet: 2381 Shrider Rd.

Project/Location:

Count Location:	Shrider Rd.	Average Speed (direction):	40mph (EB)
Count Date:	10/2/2018	Average Speed (direction):	41mph (WB)
Duration:	24 Hours	Mode Speed (direction):	40mph (EB)
Weather:	Fair	Mode Speed (direction):	40mph (WB)
ADT/Direction:	269/EB	% Exceeding Posted Speed (direction):	90.23% (EB)
ADT/Direction:	187/WB	% Exceeding Posted Speed (direction):	89.78% (WB)
ADT/Combined:	456	Top 15% Speed Exceeds (direction) :	47.50 (EB)
Posted Speed:	25 mph	Top 15% Speed Exceeds (direction) :	49.66 (WB)
Roadway Width:	24 feet		

Adjusted Avg. Speed	40mph
Average Travel Speed:	41mph
Mode Speed Average:	40mph

Comments:

Double-Yellow Centerline
No On-Street Parking
No Curb/Gutter/Sidewalk
Horse and Ped Traffic
4-Way Stop at Stinson
1 Speed-Related Accident (3YR)